


# SUPPORT NOTE

5 NOVEMBER 2013

## GEO 7X HANDHELD: SERIAL PORT PINOUTS

This document describes the pinouts on the optional USB to Serial converter cable (P/N 88049-03) for the Trimble® Geo 7X handheld.

The pins on the DE-9 connector on the USB to Serial converter cable are numbered as follows:



The pinouts for the USB to Serial converter cable (P/N 88049-03) are:

DE9 pin number	Signal
1	CD
2	Rx
3	Tx
4	DTR
5	GND
6	DSR
7	RTS
8	CTS
9	RI

This document is for informational purposes only and is not a legally binding agreement or offer. Trimble makes no warranties and assumes no obligations or liabilities hereunder.

Geospatial Division, 10368 Westmoor Drive, Westminster, CO 80021, USA

© 2013, Trimble Navigation Limited. All rights reserved. Trimble and the Globe & Triangle logo are Trademarks of Trimble Navigation Limited registered in the United States and in other countries. All other trademarks are the property of their respective owners. SUP29153 (11/13)

